



## **BENCHMARK SERVICES, INC.**

---

6635 Boykin Road • Theodore, AL 36582  
Phone: (251) 653-7235 • Fax: (251) 653-5847  
email: info@oilflush.com

# **Benchmark's High Velocity Oil Flush System:**

## ***Stop Forced Outages Due to Oil Contamination!***

Our service greatly reduces bearing and rotor scoring from particulate contamination

## ***Avoid costly oil replacement and oil disposal cost!***

Your turbine oil will meet or *exceed* the turbine's OEM oil specification and the oil manufacturer's cleanliness criteria, thereby eliminating the need to replace and dispose of your current operating oil.

## ***When is a Benchmark Flush Necessary?***

- Excessive Bearing & Rotor Scoring
- Badly Discolored and/or Scorched Oil
- Sticky & Unreliable Control Actuation
- Visible particulate and/or water contamination
- System Flushes That take Too Long
- Excessive Generator Seal Wear